



WYNDHAM



ENCORE

FABRIC CARE INFORMATION • Use mild detergents. • No chlorine bleach. • Machine wash to 120°F. • Do not overload dryer. • Tumble dry to 120°F. • Reversing cycle prevents tangles. • Tumble through cool-down cycle. • Remove immediately and hang. • If necessary, touch-up with cool iron... • Excessive heat, loading or time in dryer detracts from permanent press characteristics. • Custom colors available. • Dye lots may vary.

Wenger®

WENGER CORPORATION
555 Park Drive, PO Box 448
Owatonna, MN 55060-0448
Phone 800.4WENGER (493.6437)
Fax 507.455.4258
Customer Service 800.887.7145

U.S.A./03-07/500/089D577-01
©2007 Wenger Corporation

CANADA
219 Dufferin
Suite 117C
Toronto, Ontario, Canada M6K 3J1
Phone 800.268.0148
Fax 416.754.3996

WENGER CORPORATION
BEIJING REPRESENTATIVE OFFICE
Tel 0086-10-84972502
Fax 0086-10-84972575

WORLDWIDE
Phone 507.455.4100
Fax 507.444.0685

Web Site
wengercorp.com



ALL SNAP DRAPE FABRICS ARE DURABLY FLAME RETARDANT FOR THE SAFETY OF YOU AND YOUR GUESTS



089D577

WYNDHAM & ENCORE